

Hertzian contact fatigue failure of a large roller. The fatigue crack originated from the interior where shear stress is maximum. Several rollers failed; each costing \$750,000. (photo credit: Peter Chamberlain)

